


**Pressure Sensor
For Air**

Series *PSE 510*

How to Order



Operating pressure

0	High pressure (0 to 1 MPa)
1	Vacuum (-101 to 0 kPa)
2	Low pressure (0 to 100 kPa)

Porting

R06	ø6 reducer
M5	M5 X 0.8
01	R(PT) 1/8, M5 X 0.8
T01	NPTF 1/8, M5 X 0.8



For safety precautions, precautions for products, product specifications, external dimensions, and model selection procedures, see the comprehensive catalog (Best Pneumatics) or the catalog for each individual product.